

MIRROR/WINDOW CONTROLLER

SERVICE BULLETIN


(Tollway Defeat)

Intellitec part No# 00-00292-100, 00-00292-200 and 00-00368-000
Fleetwood part No# F22-2096, F22-8000 and F22-2098

To defeat the Tollway feature, cut leg of resistor marked R16, a 220 ohm resistor, from the unit

Note: Only one end of the resistor need be cut.

*Cut R16 to defeat
Tollway feature.*



Intellitec

1485 Jacobs Rd.
Deland, FL 32724
386.738.7307