

ECC 120VAC LINE SENSOR

WIRING DIAGRAM

INSTALLATION

- 1) Remove the small pug key from the position between the black and red wire on the original power connector. Plug the gray wire from the 120 VAC sensor into that position. Make sure that the tang on the back of the contact faces the slot on the side of the connector shell.
- 2) Connect the black wire from the 120 VAC line sensor to Power Ground.
- 3) Plug the AC line plug from the 120 VAC line sensor into a 120 VAC source which is active when shore power is available, or the GenSet is running.

